

**Draft 4-15-02**

April 16, 2002

Re: Headgate and Measuring Device Requirements for Antelope Creek Diversions,  
Water District 34, Big Lost River and Tributaries

Dear Water User,

It is the understanding of the Idaho Department of Water Resources (IDWR) that water right holders who met at the annual district meeting last month adopted a resolution providing that the watermaster of Water District 34 hire an assistant to regulate water deliveries on Antelope Creek. The users present at the meeting also adopted a resolution requiring users to install measuring devices. It is the Department's further understanding that a number of users have complied with the resolution requiring measuring devices but that there are still some Antelope Creek water users who have not yet taken action on this matter. It is our further understanding that many of the diversions on Antelope Creek lack adequate headgates or controlling works.

Last year, as in other recent drought years, IDWR and the water district received an increased number of complaints from users within the district regarding water delivery problems and potential inappropriate diversions. It is apparent that water supplies this year will again be below normal and that there will be additional pressures and calls for delivery of water. It is important that the watermaster and his assistant on Antelope Creek have an ability to measure and control diversions. The watermaster simply cannot perform his or her duty without such devices.

The purpose of this letter is to advise all users owning or operating diversions from Antelope Creek that both the water district and IDWR expect compliance with the adopted resolutions of the district. Additionally, Section 42-701, Idaho Code (copy enclosed) requires that all water users diverting water from public sources shall maintain to the satisfaction of the director of the department suitable headgates and measuring devices at the point of diversion. IDWR requests that all users diverting water from Antelope Creek implement the following steps:

- 1) Install measuring devices of a type acceptable to the department for all diversions on Antelope Creek on or before May 20, 2002
- 2) Install on or before June 15, 2002, controlling works or headgates on all Antelope Creek diversions. Such headgates or controlling works must be capable of being locked.

The watermaster may cease delivery of water to any Antelope Creek diversion that is not in compliance with the water district resolution requiring installation of

headgates. Pursuant to Section 42-701, Idaho Code, users who neglect to comply with this notice regarding installation of both measuring devices and controlling works may be subject to the administrative enforcement actions provided by Section 42-1701B, Idaho Code. Enforcement actions may include the issuance of Notices of Violation and Cease and Desist Orders, as well as possible civil penalties.

The department asks for your full cooperation concerning this matter. If you have questions concerning this matter please contact me directly at the above location or contact Doug Rosenkrance, Water District 34 watermaster, in Mackay at 588-3137.

Respectfully,

Tim Luke  
Manager, Water Distribution Section

Cc: Doug Rosenkrance, Watermaster  
IDWR Eastern Region

D:\Data\MS Word 97\WtrDistricts\WD34\Wd34-Antelope-4-10-02.doc

**State of Idaho****DEPARTMENT OF WATER RESOURCES**

1301 North Orchard Street, Boise, ID 83706 - P.O. Box 83720, Boise, ID 83720-0098  
Phone: (208) 327-7900 Fax: (208) 327-7866 Web Site: [www.idwr.state.id.us](http://www.idwr.state.id.us)

**DIRK KEMPTHORNE**  
Governor

**KARL J. DREHER**  
Director

April 18, 2002

Re: Headgate and Measuring Device Requirements for Antelope Creek Diversions,  
Water District 34, Big Lost River and Tributaries

Dear Water User,

It is the understanding of the Idaho Department of Water Resources (IDWR) that water right holders who met at the annual district meeting last month adopted a resolution providing that the watermaster of Water District 34 hire an assistant to regulate water deliveries on Antelope Creek. The users present at the meeting also adopted a resolution requiring users to install measuring devices. It is the Department's further understanding that a number of users have complied with the resolution requiring measuring devices but that there are still some Antelope Creek water users who have not yet taken action on this matter. It is our further understanding that many of the diversions on Antelope Creek lack adequate headgates or controlling works.

Last year, as in other recent drought years, IDWR and the water district received an increased number of complaints from users within the district regarding water delivery problems and potential inappropriate diversions. It is apparent that water supplies this year will again be below normal and that there will be additional pressures and calls for delivery of water. It is important that the watermaster and his assistant on Antelope Creek have an ability to measure and control diversions. The watermaster simply cannot perform his or her duty without such devices.

The purpose of this letter is to advise all users owning or operating diversions from Antelope Creek that both the water district and IDWR expect compliance with the adopted resolutions of the district. Additionally, Section 42-701, Idaho Code (copy enclosed) requires that all water users diverting water from public sources shall maintain to the satisfaction of the director of the department suitable headgates and measuring devices at the point of diversion. IDWR requests that all users diverting water from Antelope Creek implement the following steps:


- 1) Install measuring devices of a type acceptable to the department for all diversions on Antelope Creek on or before May 20, 2002
- 2) Install on or before June 15, 2002, controlling works or headgates on all Antelope Creek diversions. Such headgates or controlling works must be capable of being locked.

The watermaster may cease delivery of water to any Antelope Creek diversion that is not in compliance with the water district resolution requiring installation of

headgates. Pursuant to Section 42-701, Idaho Code, users who neglect to comply with this notice regarding installation of both measuring devices and controlling works may be subject to the administrative enforcement actions provided by Section 42-1701B, Idaho Code. Enforcement actions may include the issuance of Notices of Violation and Cease and Desist Orders, as well as possible civil penalties.

The department asks for your full cooperation concerning this matter. If you have questions concerning this matter please contact me directly at the above location or contact Doug Rosenkrance, Water District 34 watermaster, in Mackay at 588-3137.

Respectfully,

A handwritten signature in cursive script, appearing to read "Tim Luke".

Tim Luke  
Manager, Water Distribution Section

Cc: Doug Rosenkrance, Watermaster  
IDWR Eastern Region

CERTIFICATE OF SERVICE

I DO HEREBY CERTIFY that on this 18th day of April, 2002, the attached correspondence was served upon the following individuals by placing a copy of the same in the United States Mail, postage prepaid and properly addressed as follows:

Dale Huffaker  
Route 1 Box 56  
Moore, ID 83255  
554-3100

Alvin Crawford  
3943 Antelope Road  
Moore, ID 83255

Randy Purser  
Route 1 Box 120  
Moore, ID 83255

Milton Reese  
HC 60 Box 270  
Moore, ID 83255

Preston Bell  
Route 1 Box 56  
Moore, ID 83255

Robert Shawver  
143 S 1200 W  
Blackfoot, ID 83221

Jack Horton  
General Delivery 19501 Jackknife LN  
Moore, ID 83255 OLA, ID

David Keele  
HC 60 Box 231  
Moore, ID 83255

Smith Ranches  
C/o Harold Smith  
4557 Antelope Road  
Moore, ID 83255

Tim Sayer  
Antelope Road  
Moore, ID 83255

Jack Harrop  
4554 Cherry Creek Road  
Moore, ID 83255

Antelope Valley Ranch  
C/o Mike Seal  
HC 60 Box 257  
Moore, ID 83255

Craig Clark  
P. O. Box 65  
New Castle, UT 84756

John King  
Route 1 Box 280  
Moore, ID 83255

Mike Dotzenrod  
Madhavi Bradford 3776 W 3700 N  
Moore, ID 83255

Mickey King  
General Delivery  
Moore, ID 83255

Robert Waddoups  
Route 1 Box 42  
Moore, ID 83255



Dayna M. Ball, Office Specialist II  
Water Distribution Section